"Green Hill" Slave Quarters Virginia Road No. 728 Long Island Vicinity Campbell County Virginia HABS NO. VA-607
HABS
VA
16-LONI.V,

# PHOTOGRAPHS WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Eastern Office, Division of Design and Construction
143 South Third Street
Philadelphia 6, Pennsylvania

### HISTORIC AMERICAN BUILDINGS SURVEY



## "GREEN HILL" SLAVE QUARTERS

Address:

Virginia Road No. 728, Long Island Vicinity,

Campbell County, Virginia.

Present Owner:

L. H. Holland and brothers

Present Use:

Chicken House. Used by owners.

## HISTORICAL INFORMATION

"Green Hill" plantation was built by Samuel Pannill who first bought 600 acres from William and Moses Fuqua in 1797, and added to and developed the plantation 'til his death in 1864.

## ARCHITECTURAL INFORMATION

#### A. General Statement

- 1. Architectural character: This small frame building has changed very little from its early form, although it is now in poor condition and used as a chicken house.
- 2. Condition of fabric: Exterior in poor condition. Framing appears to sound.

#### B. Technical Description of Exterior

- 1. Overall dimensions: Approximately 14' x 20', 1-1/2 stories high.
- 2. Foundations: Field stone, dry construction.
- 3. Wall construction: Frame with 3" x 4" stud walls and rafters. Walls covered with weatherboarding, not original.
- 4. Stoops: Large stepping stone at doorway.
- 5. Chimneys: One stone chimney centrally located in east end. Flue is starting to fall in near top.
- 6. Openings;
  - a. Doorways and doors: One exterior door located slightly off-center in south wall. Original board and batten door still in place.

16 LONG

b. Windows and shutters: Three window openings on first floor; one opening located in east wall, north of chimney; one opening in north wall centered in wall; one opening in center of west wall in the gable ends; on second floor, two single sash windows located one in east wall north of chimney and one in west wall. Exterior trim remaining on windows. Some sash without glass in two openings. No evidence of shutters used.

#### 7. Roof:

- a. Shape, covering: Gable roof presently covered with sheet metal.
- b. Eaves: Boxed eaves formed by second floor joists projecting about 10", covered with a beaded fascia board and soffit. Tapered and beaded verge board on gable ends. Ends of eaves covered by extension of weatherboarding and verge boards rather than a cover board.
- C. Technical Description of Interior: Interior was not investigated. Presently in use as a chicken house. Has wooden floor.

Prepared by Orville W. Carroll, Architect National Park Service October 1960.